




# TECH BULLETIN

084  
11/99

*Published regarding engineering changes and improvements*

## SUBJECT: Crankcase Change - 60 Frame

The 60 Frame Crankcase lifting eye bolt has been relocated to a more forward position. This has been done to provide better balance with the increase popularity of the block-style heads. This change will take place approximately January 2000 and the crankcase PN 43284 will continue to be used. A recess has also been added at the top of the crankcase for the label.



CAT PUMPS  
Technical Services Department